

Transmission/Driveline**Rating: Green = Go****Steering/Suspension****Rating: Green = Go****Body****Rating: Green = Go**

Minor defects and panel repairs of a satisfactory nature may not be recorded

Severity	Section	Part/Location	Fault/Comment
O	PAINTWORK/PANELS	Various panels	has minor scratches and stone chips

Tyres

Severity	Section	Part/Location	Fault/Comment
O	TYRES	RH front tyre	becoming low in tread
I	TYRES	LH front tyre	worn low at edge/s
O	TYRES	Rear tyres	sidewalls are splitting

Wheels

Severity	Section	Part/Location	Fault/Comment
O	WHEEL RIMS	Rims Various	scrape marks evident
I	WHEEL RIMS	Rims Pass/Side, Both	slight distortion at inner rims

Electrical

Severity	Section	Part/Location	Fault/Comment
O	PARK/TAIL LIGHTS	Park lamp Driv/Side, Front	operational
O	STOP LIGHT/S	Operation Pass/Side	operational
I	WIPERS & WASHERS	Wiper blade/s	smearing